



Historic England

# TOWN END FARMHOUSE AND ADJOINING FARM BUILDING TO SOUTH

## Overview

Heritage Category:

Listed Building

Grade:

II

List Entry Number:

1294359


Date first listed:

27-Sep-1984

Statutory Address:

TOWN END FARMHOUSE AND ADJOINING FARM BUILDING TO SOUTH, WESTWAY

## Map





© Crown Copyright and database right 2019. All rights reserved. Ordnance Survey Licence number 100024900.

© British Crown and SeaZone Solutions Limited 2019. All rights reserved. Licence number 102006.006.

Use of this data is subject to **Terms and Conditions** (<https://historicengland.org.uk/terms/website-terms-conditions/>)

The above map is for quick reference purposes only and may not be to scale. For a copy of the full scale map, please see the attached PDF - **1294359 .pdf**

([http://mapservices.HistoricEngland.org.uk/printwebservice/StatutoryPrint.svc/267871/HLE\\_A4L\\_Grade|HLE\\_A3L\\_Grade.pdf](http://mapservices.HistoricEngland.org.uk/printwebservice/StatutoryPrint.svc/267871/HLE_A4L_Grade|HLE_A3L_Grade.pdf))

The PDF will be generated from our live systems and may take a few minutes to download depending on how busy our servers are. We apologise for this delay.

This copy shows the entry on 27-Aug-2019 at 20:04:11.

## Location

### Statutory Address:

TOWN END FARMHOUSE AND ADJOINING FARM BUILDING TO SOUTH, WESTWAY

The building or site itself may lie within the boundary of more than one authority.

### County:

North Yorkshire

### District:

Hambleton (District Authority)

### Parish:

Crayke

### National Grid Reference:

SE 56061 70383

## Details

SE 5670 CRAYKE WESTWAY 7/21 (east side) Town End Farmhouse and adjoining farm building to south GV II

Farmhouse. Probably mid C18 with heightening of about 4 courses at eaves and some rebuilding of upper parts of gable ends in early C19. Reddish-brown local brick, 3-course 1st floor band. Sandstone quoins to lower part north side. Pantile roof with end chimneys. Two storeys, 2 bays. End entrance has 4-panel door under flat brick arch. Modern casements under brick soldier arches. Remains of bricked up window above entrance. South gable: remains of tumbled in brickwork. Adjoining to south: farm building, probably former

bricked-up window above entrance. South gable, remains of tumbled-in brickwork. Adjoining to south, farm building, probably former stable and hayloft. Early C19. Reddish-brown brick. Pantile roof. Two storeys. Wagon entrance to left. Remains of several segmental brick arches. Three 1st floor windows with wooden shutters. Included for group considerations.

Listing NGR: SE5606170383

## Legacy

The contents of this record have been generated from a legacy data system.

Legacy System number:

333421

Legacy System:

LBS

## Legal

This building is listed under the Planning (Listed Buildings and Conservation Areas) Act 1990 as amended for its special architectural or historic interest.

End of official listing

## Images of England

Images of England was a photographic record of every listed building in England, created as a snap shot of listed buildings at the turn of the millennium. These photographs of the exterior of listed buildings were taken by volunteers between 1999 and 2008. The project was supported by the Heritage Lottery Fund.

Date: 25 Jan 2001

Reference: IOE01/03467/05

Rights: Copyright IoE Mr John Turner. Source Historic England Archive

Archive image, may not represent current condition of site.

© Historic England 2019